

## ● Anthracite

<u>Properties:</u>	Wear resistant coating. Good corrosion resistance.
<u>Appearance:</u>	Dark grey to blackish, shiny surface
<u>Base material:</u>	Anthracite tin/nickel may be plated on nickel, copper and brass.
<u>Application:</u>	Decorative purposes for an exclusive appearance.

